




Federal Highway Administration

5th Biennial Workshop


INTERSTATE
TECHNICAL
GROUP ON
ABANDONED
UNDERGROUND
MINES




### Geologic Period of Michigan Bedrock




#### Michigan Rock Formations








### Chapin Mine, Iron Mountain, MI





—Gordon Sullivan Photo Picture shows the collapse of the Chapin pit highway crossing on Stephenson avenue yesterday afternoon. Whether the cavein was due to a sluffing out of the crossing fill or a breaking down of the old mine workings is not determined. Water at the right of the picture is about 90 feet deep, with the level being only 40 feet from the surface of the roadway. Previous to the shutdown of the Chapin mine several years ago and the suspension of pumping the pits were dry. Picture clearly indicates how the water has risen since then, finally ending in the washout of this portion of Iron Mountain's principal street. Four cars and one truck are buried somewhere in this cavein and whether they can be salvaged is still an unan-




















### Michigan Abandoned Mine Lands Inventory



Michigan Abandoned Underground Mine Inventory was produced for the Land and Mineral Services Division, Michigan Department of Natural Resources, Lansing, Michigan.

Michigan Underground Abandoned Mines Inventory Department of Mining Engineering, Michigan Technological University

Phone: 906/487-2610


Email (about the web site): mining@mtu.edu

# Michigan Abandoned Mine Lands Inventory





Mine Hazard Awareness Campaign Fact Sheet





### Michigan Mine Inspectors

Marquette County	Mine Inspector John E. Carlson 806 N. Second Street Ishpeming, MI 49849 Phone 485-1392	Underground iron mines, several other metallic exploration shafts
Iron County	Mine Inspector Peter Korach 1904 Pisoni Street Iron River, MI 49935 906-265-9011 <a href="http://www.iron.org/government/mine_inspector.htm">http://www.iron.org/government/mine_inspector.htm</a>	Underground iron mines
Dickinson County	Mine Inspector Frank Santini 501 E. Blaine St. Iron Mountain, MI 49801 906-774-6095	Underground iron mines
Baraga County	Mine Inspector Charles Sliger (906) 355-2516	Underground iron mines
Houghton County	Mine Inspector Sulo Hiltunen 482-2484	Underground copper mines

### Salt Mining in Michigan







### **Brief History**

A radical change in salt production occurred in 1906 when the Detroit Salt and Manufacturing Company started sinking a shaft for underground mining of rock salt. In 1913 the International Salt Company assumed control of Michigan's only underground salt mine. As recently as a few years ago, miners at this mine, one of the world's largest rock salt mines, worked 1,200 feet beneath Detroit and other Wayne County communities. The mine, which consists of 100 miles of tunnels, has never experienced a collapse or mine fatality. The mine was closed in the 1980's but has now been reopened and is in operation.

## Three important factors lie behind the location and development of the Detroit salt mining area:

- A healthy market requiring salt for the meat processing industry, chemical industry, water softening snow and ice removal from roads and highways.
- 2) Abundant salt at a reasonable depth and of sufficiently high quality to permit economical mining,
- 3) The availability of low cost water transportation on the Great Lakes which facilitates the movement of salt in Canada from eastern Saskatchewan Province to western Quebec Province, and in the U. S. from the "Dakotas" to western New York State.

